ocope oi	Work for Property Loc			5128 North 24th Pla	<u>50</u>	
	Property is: Single Fan	nily 🗹	Duplex	☐ Other ☐		
Date:	2/11/2014	<u> </u>				
take no respo		after the ins	spection da	ite, or for omissions through erro	edevelopment Authority, and their represe or or oversight. The list does not necessa grams.	
Exterior	Condition Report					
Location Site	Required Work Landscaping	n/a ☑	Yes 🗌	Note/Comments Self Help	\$	Cost
	Steps/Handrails	n/a ✓	Yes 🗌		\$	
	Service walks	n/a ✓	Yes 🗌		\$	
	Fencing	n/a ☑	Yes 🗌		\$	
	Parking	n/a ☑	Yes 🗌		\$	
	Retaining walls	n/a ✓	Yes 🗌		\$	
	Other	n/a 🗌	Yes \square		\$	
_	Other	n/a 🗌	Yes 🗌		\$	
Garage	Singles: repair	n/a ☑	Yes 🗌		\$	
	Shingles: Roof over existing	n/a ✓	Yes 🗌		\$	
	Shingles:Tear off & re-roof	n/a 🗌	Yes ✓		\$	2,500.00
	Gutters/downspouts	n/a	Yes ✓		\$	550.00
	Flashing	n/a ☑	Yes 🗌		\$	
	Eaves	n/a 🗌	Yes ✓		\$	850.00
	Siding	n/a	Yes ✓		\$	4,500.00
	Doors	n/a	Yes ✓		\$	1,500.00
	Windows	n/a	Yes 🗸		\$	250.00
	Slab	n/a ✓	Yes 🗌		\$	
	Paint	n/a	Yes ✓		\$	750.00
	Electrical	n/a ✓	Yes 🗌		\$	
	Other	n/a	Yes ✓	structural repairs and hou	use #'s \$	2,000.00
Porches	Roof	n/a ☑	Yes 🗌		\$	
	Deck-upper	n/a ✓	Yes 🗌		\$	
	Decklower	n/a ✓	Yes 🗌		\$	
	Steps/handrails	n/a ✓	Yes 🗌		\$	
	Ceiling	n/a ✓	Yes 🗌		\$	
	Guardrails	n/a ✓	Yes 🗌		\$	
	Structural	n/a ✓	Yes 🗌		\$	
	Paint	n/a ✓	Yes 🗌		\$	

n/a 🗌 Yes 🗌

\$

Other

House

Chimney	n/a ☐ Yes ☑ repairs	\$ 550.00
Shingles: repair	n/a ☑ Yes 🗌	\$
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 8,000.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 850.00
Flashing	n/a ☑ Yes 🗌	\$
Eaves	n/a ☐ Yes ☑	\$ 800.00
Siding	n/a ☑ Yes 🗌	\$
Storm Doors	n/a ☑ Yes 🗌	\$
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 900.00
Storm Windows	n/a ☐ Yes ☑	\$ 450.00
Prime ("main") Windows	n/a ☐ Yes ☑	\$ 5,000.00
Paint	n/a ☐ Yes ☑	\$ 850.00
Foundation	n/a ☑ Yes 🗌	\$
Electrical	n/a ☑ Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a ☐ Yes ☐	\$
Other	n/a ☐ Yes ☐	\$

Exterior: Estimated Cost:* \$ 30,300.00

 $\mbox{\ensuremath{^{\star}}}\mbox{average contracted cost.}$ Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report Unit: Entire unit (single family)	7			Lower unit of duplex	
Mechanical Heating	Upper unit of duplex Required Work				Other	
J	Repair/replace boiler	n/a ✓	Yes			\$
	Repair radiation	n/a ✓	Yes			\$
	Repair/replace furnace	n/a 🗌	Yes	V		\$ 3,000.00
	Repair ductwork	n/a ✓	Yes			\$
	Replace thermostat	n/a 🗌	Yes	V		\$ 100.00
	Repair/replace grilles	n/a	Yes	V		\$ 350.00
Electrical	Tune boiler/furn. insp ht exchang	ın/a ✓	Yes			\$
Licotrical	Repair/replace receptacles	n/a 🗌	Yes	V		\$ 500.00
	Repair/replace switches	n/a ✓	Yes			\$
	Repair/replace fixtures	n/a	Yes	V		\$ 500.00
	Install outlets and circuits	n/a ✓	Yes			\$
	Install outlets and circuits	n/a ✓	Yes			\$
	Install outlets and circuits	n/a ✓	Yes			\$
	Install outlets and circuits	n/a ✓	Yes			\$
	Upgrade service	n/a ✓	Yes			\$
	Other	n/a 🗌	Yes			\$
Diversities	Other	n/a	Yes			\$
Plumbing	Repair/replace kitchen sink	n/a 🗸	Yes			\$
	Repair/replace kitchen sink fauce	n/a 🗌	Yes	√	and drain	\$ 650.00
	Repair/replace tub	n/a ✓	Yes			\$
	Repair/replace tub faucet	n/a	Yes	V		\$ 450.00
	Repair/replace toilet	n/a ✓	Yes			\$
	Repair/replace lavatory	n/a	Yes	V		\$ 350.00
	Repair/replace lavatory faucet	n/a 🗌	Yes	√		\$ 300.00
	Repair/replace wash tub	n/a 🗸	Yes			\$
	Repair/replace wash tub faucet	n/a ☑	Yes			\$
	Unclog piping:	n/a ✓	Yes			\$
	Repair drain/waste/vent piping	n/a ✓	Yes			\$
	Repair water piping	n/a ✓	Yes			\$
	Repair/replace water heater	n/a 🗌	Yes	V		\$ 850.00
	Other	n/a 🗌	Yes	V	tub surround	\$ 450.00

n/a ☐ Yes ☐ \$

Other

Windows								
	Replace broken glass	n/a	J	Yes			\$	
	Repair or replace sash	n/a	V	Yes			\$	
Doors								
	Repair or replace doors	n/a		Yes	V		\$	400.00
	Repair or repl. locks/latches	n/a		Yes	✓	Self Help	\$	250.00
Walls/Ceiling			_		_		_	
	Repair or repl. @ defective	n/a	Ш	Yes	1		\$	2,000.00
Paint	Repair or repl. @ defective	n/a		Yes	✓		\$	850.00
Fire Safety								
· ···· · · · · · · · · · · · · · · · ·	Install smoke/CO alarm:bsmt.	n/a		Yes	V	Self Help	\$	40.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	40.00
	Install smoke/CO alarm: 2nd flr.	n/a	V	Yes		Self Help	\$	
Handrails	Repair/replace defective	n/a		Yes	V	Self Help	\$	125.00
Stairs	Repair defective	n/a		Yes			\$	
Floors	Repair defective	n/a		Yes	7		\$	2,200.00
Other	•						· ·	,
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
						Interior: Estimated Cost:	\$	13,405.00
						Total Exterior and Interior Cost:*	\$	43,705.00
						*average contracted cost. Actual costs may vary. Self help will reduce	he amount.	

Inspected by: Mark Pelzek Date: 2/11/14

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.